



Remove protective cover and set aside. Carefully unclip lightning protector tape during works to redecorate timber etc. Re fix tape and cover upon completion. Note – the contractor is responsible for ensuring the tape is not damaged during the works.

Recheck condition at commencement, but not work included.

Carefully remove bricks from bulging panel.

Allow for face indent repair to bottom of front face approx. 800 x 100 x 50mm

Allow for face indent repair to front face approx. 800 x 250 x 75mm – allow for up to lap joint on left

South Elevation  
(Not to scale)

ST JAMES THE GREAT, HAYDOCK – SOUTH WALL REPAIRS

DRAWING 02 – ELEVATION SHOWING GENERAL REPAIRS (1 of 2)

